



**MALAYSIA MARINE DEPARTMENT**  
MARINE HEADQUARTERS, MENARA DIUS API  
PT 664, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS

**NTM 205(T)/2024**

Telefon : 03-3346 7777 Emel : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

---

Authority : Director of Marine, Malaysia

Position : Malacca Strait

Charts Affected : MAL 54 & MAL 540  
BA 3901 & BA 3945

---

### **ONE FATHOM BANK LIGHTHOUSE UNRELIABLE MALACCA STRAIT**

---

Mariners are advised that the One Fathom Bank lighthouse is unreliable due to essential maintenance works with a revised nominal range of 16Nm. The details are as follows:

**Name** : **ONE FATHOM BANK**  
**Position** : Lat 02° 53.31' N  
Long. 100° 59.72' E ( *Datum: WGS-84* )  
**Light Character** : FL(4) W 20S  
**Range** : **16 Nm**

Marines are advised to navigate with extra caution.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department.  
15<sup>th</sup> October 2024