



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 34(T)/2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kemaman Port
Charts Affected : MAL 6416
 BA 1374

**KEMAMAN BREAKWATER SOUTH LIGHT BEACON UNLIT
TERENGGANU WATERS**

Mariners are advised that Kemaman Breakwater South light beacon is unlit

Name : Kemaman Breakwater South
Position : Lat. 04° 13.768' N
 Long. 103° 27.127' E
Light Characteristic : FL.Y.3s

Mariners are advised to navigate with caution in the area.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
28th February 2024.

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602