



**MALAYSIA MARINE DEPARTMENT**  
MARINE HEADQUARTERS, MENARA DIUS API  
P.O BOX 664, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



**PENINSULAR NOTICE TO MARINERS      NTM 34(T)/2024**

Telefon           : 03-3346 7777   Emel            : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili       : 03-3168 5289   Laman Web   : <http://www.marine.gov.my>

Authority           : Director of Marine, Malaysia  
Position            : South China Sea, Kemaman Port  
Charts Affected    : MAL 6416  
                          BA 1374

**KEMAMAN BREAKWATER SOUTH LIGHT BEACON UNLIT  
TERENGGANU WATERS**

Mariners are advised that Kemaman Breakwater South light beacon is unlit

Name                : Kemaman Breakwater South  
Position            : Lat.    04° 13.768' N  
                          Long. 103° 27.127' E  
Light Characteristic : FL.Y.3s

Mariners are advised to navigate with caution in the area.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department.  
27<sup>th</sup> February 2024.

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602