



**MALAYSIA MARINE DEPARTMENT**  
MARINE HEADQUATERS, MENARA DIUS API  
P.O BOX 664, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



**PENINSULAR NOTICE TO MARINERS    NTM 51/2024**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web     : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia  
Position           : South China Sea, Kerteh Port  
Charts Affected   : MAL 6436  
                          BA 1374

---

**KERTEH PORT NO.5G LIGHT BUOY RESTORED TO NORMAL  
SOUTH CHINA SEA**

---

Mariners are advised that Kerteh Port No.5G light buoy has been restored to normal.  
The details are as follows:

Name               : **Kerteh Port No.5G (KP5G)**  
Position           : **Lat. 04° 35.162' N**  
                          **Long. 103° 28.063' E**  
                          *(Datum: WGS-84)*  
Light Characteristic : **Fl.G.5s** ( *Starboard Hand* )

Mariners are advised to navigate with caution when in the vicinity.  
This notice cancels NTM 38(T)/2024.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department.  
13<sup>th</sup> March 2024