



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 53/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea, Kertih Port

Charts Affected : MAL 6436
 BA 1374

**KERTEH PORT NO.6R LIGHT BUOY RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Kerteh Port No.6R light buoy has been restored to normal.
The details are as follows:

Name : **Kerteh Port No.6R**
Position : **Lat. 04° 35.047' N, Long. 103° 27.588' E**
 (*Datum: WGS-84*)
Light Characteristic : **Fl(2).R.4s**

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 276(T)/2023.

(EMIZUL FADLY MASDEK)
for The Director General,
Marine Department Malaysia.
13th March 2024