



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 54/2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kelantan Waters
Charts Affected : MAL 664
 : BA 3543

**TUMPAT WRECK LIGHT BUOY RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Tumpat Wreck light buoy is restored to normal. The details are as follows:

Name : Tumpat Wreck (TW)
Position : Lat. 06° 14.300' N,
 Long. 102° 09.190' E
Light Characteristic : Fl.G.5s
Description : Star Board Hand

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 06(T)/2024.

(TS. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department.
14th March 2024