



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS - NTM 80 (T) / 2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6359
BA 3446

SUNGAI KUANTAN OUTER LIGHT BUOY UNLIT
SOUTH CHINA SEA

Mariners are advised that Sungai Kuantan Outer Light Buoy is unlit.

Name : Sungai Kuantan Outer Light Buoy

Position : Lat. 03° 47.010' N
Long. 103° 21.350' E

Light Characteristic : Fl.G.10s

Mariners are advised to navigate with caution in the area.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department
3th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602