



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 36/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters

Charts Affected : MAL 5129 & MAL 515
BA 3947

PTP NO.2 LIGHTBUOY REPLACED IN POSITION JOHOR WATERS

Mariners are advised that PTP No.2 Lightbuoy has been replaced in position.

Name : PTP No.2 Lightbuoy
(*Port*)

Position : Lat. 01° 16.060' N
Long. 103° 32.57' E

Light Characteristic : FL.R.2s

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels NTM 191(T)/2022.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
28th February 2024