



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 102/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kuala Rompin
Charts Affected : MAL 635
BA 3445

**BATUAN PONTIAN LIGHT BEACON RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Batuan Pontian Light Beacon has been restored to normal.

Name : Batuan Pontian
Position : Lat. 02° 45.378' N
Long. 103° 36.688' E

Light Characteristic: Fl.W.5s

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
28th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602