



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 100/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kuantan Port, Pahang

Charts Affected : MAL 6359
 BA 1379

**SOUTH BREAKWATER HEAD LIGHT BEACON RESTORED TO NORMAL
KUANTAN PORT, PAHANG**

Mariners are advised that Kuantan South Breakwater Head Beacon has been restored to normal. The details are as follows:

Name : Kuantan South Breakwater Head Beacon

**Position : Lat. 03° 58.080 N
 Long. 103° 26.610 E**

Light Characteristic : Fl.(4) R.12s

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Marine Department Malaysia.
27th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602