



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 123/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6522
BA 3446

**BUKIT PUTERI LIGHT BEACON RESTORED TO NORMAL
SOUTH CHINA SEA**

Mariners are advised that Bukit Puteri Light Beacon has been restored to normal:

Name : Bukit Puteri

**Position : Lat. 02° 20.200' N
Long. 103° 08.300' E**

Light Characteristic: Fl.W.3s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 103(T)/2023.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Malaysia Marine Department
12th June 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602