



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS, MENARA DIUS API**  
**PT 664, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



**NOTICE TO MARINERS**

**NTM 167(T)/2024**

Telefon : 03-3346 7777 Emel : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters, Tg.Penyusup

Charts Affected : MAL 6124  
BA 4042 & BA 3831

**KD PENDEKAR WRECK LIGHT BUOY ESTABLISHED IN POSITION  
JOHOR WATERS**

Mariners are advised that a temporary light buoy has been established in the vicinity of KD Pendekar wreck. The details are as follows:

Name : **KD PENDEKAR WRECK**

Position : Lat. **01° 20.880'N**  
Long. **104° 18.500' E**  
(Datum: WGS-84)

Light  
Characteristic: **FL.2 W 10s**

Type : **Isolated Danger Mark**

Marines are advised to navigate with extra caution in the vicinity.

**(EMIZUL FADLY MASDEK)**  
for The Director General,  
Malaysia Marine Department.  
28<sup>th</sup> August 2024